# **Retreatment of European XFEL Series Cavities at DESY as Part of the Repair of European XFEL Accelerating Modules.**



19 (BD)\*

 $32(Q_0)$ 

31 (BD)

 $30(Q_0)$ 

36 (BD)

27 (Xray)

34 (BD)

33 (BD)

223\*\*

UGV2 in MV/m

(limitation)

 $31 (Q_0)$ 

 $36(Q_0)$ 

 $30(Q_0)$ 

34 (Emax)

33 (Emax)

39 (FE)

 $37 (Q_0)$ 

32 (FE)

272

S. Sievers<sup>†</sup>, N. Krupka, D. Reschke, S. Saegebarth, J. Schaffran, M. Schalwat, P. Schilling, M. Schmoekel, N. Steinhau-Kuehl, B. v. d. Horst, E. Vogel, H. Weise, DESY, Hamburg, Germany M. Wiencek, Instytut Fizyki Jądrowej PAN, 31-342 Kraków, Poland

## Abstract

For the European XFEL 102 accelerating modules were built and tested. Several accelerating modules had to be reworked due to different kinds of non-conformities. The extent of this rework varied greatly. At the end of production four accelerating modules could not be qualified in time before the tunnel installation was to be finished in September 2016. Meanwhile the cavity strings of two of these accelerating modules have been disassembled in the DESY clean room. The cavities have been retreated at DESY either by additional high pressure water rinsing or BCP flash chemical treatment. All cavities were vertically tested and 15 out of 16 were qualified for the reassembly of the cavity strings. One accelerating module will be reassembled completely and tested until the end of 2018; the other will follow in the first half of 2019. We report on retreatment procedures and performance of these cavities.

## **Accelerating Modules Under Repair**

*XM46* 

- Beam vacuum leak

cavities retreated

- String disassambled and

- String reassambly in Q1 2019

## XM8

- Leak in 2K area could not be verified
- Module was reassembled
- Disassembly of the cavity string 7 of 8 cavities recovered was not necessary
- XM50
- Beam vacuum leak
- String disassambled and cavities retreated
- 8 of 8 cavities recovered
- Reassambly in progress

#### *XM*99

- Beam vacuum leak still under investigation
- String disassambly and cavity retreatment planned for 2020



Reassembly of accelerating module XM50.1 (former XM50) in the Accelerator Module Test Facility AMTF

### **Retreatment Procedures**

For the retreatment of superconducting European XFEL series cavities that did not achieve the approval for string installation different retreatment passes were specified. During the repair of the accelerating modules XM46 and XM50 only the retreatment passes RP1 and RP2 were applied.

#### **Retreatment Pass RP1**

- 1. Cleaning by ultrasonic cleaning and ultrapure water rinsing to enter ISO 4 cleanroom 6. Assembly of accessories and beam tube
- Venting to normal pressure with 3 l/min Nitrogen gas flow rate

#### **Retreatment Pass RP2**

- 1. Cleaning by ultrasonic cleaning and ultrapure water rinsing to enter ISO 4 cleanroom
- 2. Venting to normal pressure with 3 l/min
  - Nitrogen gas flow rate
- 3. Dismounting of all cavity accessories
- 4. Chemical treatment of maximum removal of 10 µm by BCP, ultra-pure water rinsing and one time HPR
- 5. Drying for 12 hours in ISO 4 cleanroom area
  - flanges to cavity, leak check
- 7. Dismounting of beam tube flange short side

## **Cavity Performance**

All 16 cavities from the disassembled accelerating modules XM46 and XM50 were retreated by HPR according to retreatment pass RP1. Two of the cavities, CAV00831 and CAV00869, did not recover and were treated additionally by BCP flash chemical treatment, according to retreatment pass RP2. The usable gradients in MV/m of the cavities in the vertical test before accelerating module assembly (UGV1), in the module test (UGM) and after the retreatment (UGV2) together with the retreatment procedure are given in the tables below. The constraint which limits the usable gradient of the cavities is given in brackets. UGV2 for the cavities CAV00831 and CAV00869 were measured after the BCP treatment.

Usable gradients of the cavities from accelerating modules XM46 and XM50 before and after retreatment. \*CAV00831 is not qualified for accelerating module assembly yet. \*\*Sum of the 7 qualified cavities

Position in	Covity No.	UGV1 in MV/m	UGM in MV/m	Retreatment	UGV2 in MV/m
XM46	Cavity-INO	(limitation)	(limitation)	Procedure	(limitation)

<ol> <li>Dismounting of beam tube flange short side 8. Six times high pressure rinsing and drying for 12 hours in ISO 4 cleanroom area for 12 hours in ISO 4 cleanroom area</li> <li>Assembly of beam tube flange</li> <li>Pump down, leak check with standard turbo molecular pumping unit</li> <li>Pump down, leak check with standard turbo molecular pumping unit</li> </ol>			CAV00831	30 (Q <sub>0</sub> )	17,4 (Xray)	BCP
			CAV00869	30 (Q <sub>0</sub> )	17,6 (BD)	BCP
			CAV00051	$30 (Q_0)$	20,7 (BD)	HPR
			CAV00860	$30 (Q_0)$	24,5 (Xray)	HPR
			CAV00279	30 (Xray)	24,9 (Xray)	HPR
			CAV00261	29 (Q <sub>0</sub> )	19,8 (Xray)	HPR
	C7	CAV00850	$29 (Q_0)$	17,1 (Xray)	HPR	
Jigh Dressure Dines (UDD)	BCP Flash Chemical Treatment	C8	CAV00818	30 (Emax)	15,3 (Xray)	HPR
ngn Fressure Kinse (HFK)		Sum		238	157,3	
		Position in XM50	Cavity-No	UGV1 in MV/m (limitation)	UGM in MV/m (limitation)	Retreatment Procedure
		C1	CAV00207	36 (Emax)	20 (Xrays)	HPR
		C2	CAV00789	$38 (Q_0)$	16.4 (Xrays)	HPR
		C3	CAV00253	41 (Emax)	29.1 (BD)	HPR
		C4	CAV00256	38 (Emax)	31 (PWR)	HPR
		C5	CAV00257	40 (Emax)	31 (Xrays)	HPR
		C6	CAV00260	40 (Emax)	25.6 (Xrays)	HPR
		C7	CAV00265	36 (FE)	23.1 (Xrays)	HPR
		C8	CAV00267	37 (Q <sub>0</sub> )	20.3 (BD)	HPR
		Sum		306	196,5	
		In vertical test 1 cavities met the European XFEI phase and qual reassembly of t some did not re performance. T	5 of 16 retreate acceptance cr serial product ified for the he cavity string cover their orig he difference b	ed riteria of 8 – tion 6 – g. But 911 8 – ginal 4 –		



High pressure ultra-pure water rinsing (HPR) setup with acrylic plastic cavity model installed above the sprayhead



Buffered chemical polishing cabinet with an undressed nine-cell European XFEL cavity installed

performance. The difference between of the usable gradient in vertical test before accelerating module assembly **9** 2 and after the retreatment in the framework of the accelerating module repair efforts is compiled in the figure beside. Due to the typical uncertainties of cold rf measurements, a variation of  $\pm 10$  % of the previous performance is marked as "unchanged".



Difference in usable gradient in vertical tests before accelerating module assembly and after retreatment.

† sven.sievers@desy.de

